

# TABLE OF CONTENTS

<b>1 Chapter 1</b> General Troubleshooting	<b>49 Chapter 10</b> Blisters	<b>109 Chapter 21</b> Discoloration
<b>7 Chapter 2</b> Understanding the Molding Process	<b>55 Chapter 11</b> Blush	<b>115 Chapter 22</b> Flash
<b>17 Chapter 3</b> Venting the Mold	<b>61 Chapter 12</b> Bowling	<b>121 Chapter 23</b> Flow Lines
<b>21 Chapter 4</b> Understanding the Material	<b>67 Chapter 13</b> Brittleness	<b>127 Chapter 24</b> Gloss (low)
<b>25 Chapter 5</b> The Operator	<b>73 Chapter 14</b> Bubbles (voids)	<b>133 Chapter 25</b> Jetting
<b>27 Chapter 6</b> Recommended Melt Temperatures	<b>79 Chapter 15</b> Burn Marks	<b>139 Chapter 26</b> Knit Lines (Welds)
<b>31 Chapter 7</b> Recommended Mold Temperatures	<b>85 Chapter 16</b> Clear Spots	<b>143 Chapter 27</b> NonFill (Short Shots)
<b>33 Chapter 8</b> Glossary of Common Terms	<b>89 Chapter 17</b> Cloudy Appearance	<b>149 Chapter 28</b> Shrinkage (Excessive)
<b>43 Chapter 9</b> Black Specks	<b>95 Chapter 18</b> Contamination	<b>155 Chapter 29</b> Sink Marks
	<b>99 Chapter 19</b> Cracking/Crazing	<b>161 Chapter 30</b> Splay
	<b>103 Chapter 20</b> Delamination	<b>167 Chapter 31</b> Warpage